



1 Sauer-Danfoss HWD DP200-00-01-03-00-00 10107536 Revision History

This file contains important supplementary and late-breaking information that may not appear in the main product documentation. We recommend that you read this file in its entirety.

2 Version 10107536v110 (June 2010)

2.1 What is New

- Requires minimum 4.3.7 version of PLUS+1 GUIDE / Service Tool.
- Added a new Screen Editor image format that is optimized for the properties of the display.
- Added ECUInfoPacked support. The packed infoblock contains data about the controller, application and embedded operating system of a hardware unit.
- Increased the usable non-volatile memory area size from 1000 to 2000 bytes.
- Amber LED support has been added.
- Repeat-Until component support has been added.
- Get Time us component support has been added.
- Added validity check before the real time clock date and time is changed.

2.2 Fixes to the HWD

- Added support for all conversion characters for value formatting in text that are listed in the PLUS+1 GUIDE user manual.
- Fixed support for Multiple Read Only Parameters.
- Fixed a graphic object visible signal issue. Sometimes it falsely indicated non-visibility for visible objects.
- Fixed enabling and disabling of screen areas in modules. This bug resulted in blank screen areas without content.
- A function is introduced that shut off the frequency and count measurements when signals of a frequency above 10 kHz is inputted. This prevents the unit from stalling.
- Reduced the performance impact of high frequency signals inputted on C1p10 and C1p11.
- Fixed the %% conversion pattern for the printing of the percent sign.
- Fixed reference point issue for non rotated monochrome images.
- Fixed a issue that resulted in that applications restarted at irregular intervals.
- Fixed the previously non-functional CAN bus-off error state recovery function.
- Fixed the issue with the processing time in the cycle following the first processing time being 400 ms instead of the time requested with the OS.ExecTimeOut variable.

2.3 Known issues

- The appearance of sloped lines on the display is not always consistent with the appearance in the PLUS+1 GUIDE Screen Editor.
- The processing loop time can fluctuate slightly above the requested time set by the OS.ExecTimeOut variable.

3 Product Information on the Web

For technical information, visit the Sauer-Danfoss PLUS+1 website: (www.sauer-danfoss-plus1.com).

Telephone support can be obtained by calling:

North America: Toll free number 1-888-50PLUS1 (1-888-507-5871)

Europe: +46 476-569 06

Please report all suggested enhancements and great ideas to helpdesk@sauer-danfoss-plus1.com

Please report all defects to helpdesk@sauer-danfoss-plus1.com

4 Disclaimer

The Sauer-Danfoss Software License Agreement completely defines the licensed use of this software.

Information in this document is provided in connection with Sauer-Danfoss PLUS+1 Tool set. No license, express or implied, to any intellectual property rights is granted by this document.

Sauer-Danfoss disclaims all warranties and liabilities for the use of this document and the information contained herein and assumes no responsibility for any errors, which may appear in this document, nor does Sauer-Danfoss make a commitment to update the information contained herein. Sauer-Danfoss reserves the right to make changes to this document at any time, without notice.

5 Copyright

©2004-2010 Sauer-Danfoss, Inc. All rights reserved.

Third party trademarks and brand names are the property of their respective owners.