



OUTPUT CHARACTERISTICS



1766



1767

FAILURE MODES AND WARNING

Automatic controls are intended to move machine elements without operator input. This motion can be dangerous to persons unfamiliar with the intended control action. Exercise care when operating the automatic control.

WARNING

This control uses a sensing signal which cannot be seen. This creates an **extra** danger of unforeseen stopping and starting of machine components. Advise operators to turn the control OFF when people are near the sensor or the controlled machine element.